





2-PHASE MOTOR PINOUT

PIN 3 = +5Vdc

PIN13 = COMMON

PIN 8 = FAR LIMIT

PIN 12 = NEAR LIMIT

PIN 1 = MOTOR A+

PIN 7 = MOTOR A-

PIN 6 = MOTOR B+

PIN 11 = MOTOR B-

15 PIN HIGH DENSITY MALE D-SUB

OUTLINE

